

ND -2010-8-W 224924 001/21/10

#### C. Earl Hunter, Commissioner

Promoting and protecting the health of the public and the environment.

David Shoemaker Georgia Water and Well 259 Wynburn Avenue Athens, Georgia 30601 April 10, 2009

RECEIVED

JUL 2 0 2010

RE:

Port Bass I

System # 3750002

≓SC SC CLERK'S OFFICE

### Dear Mr. Shoemaker:

On March 31, 2009, a sanitary survey of the above referenced system was conducted by the South Carolina Department of Health and Environmental Control (Department) personnel to determine compliance with the State Primary Drinking Water Regulations. An overall rating of **NEEDS IMPROVEMENT** has been given for this survey. Following are comments and/or recommendations on items noted during the inspection. These items should be addressed immediately to help ensure that the water system is able to provide a continuous supply of safe drinking water to the customers/consumer. The headings and item numbers listed on the following page(s) correspond with the headings and item numbers listed on the enclosed Public Water System Sanitary Survey Report.

### [REMEMBER TO DISINFECT THE WELL AND SYSTEM AFTER ANY REPAIRS/UPGRADES ARE MADE TO THE WELL, STORAGE TANK, OR PIPING].

Please respond to this office, in writing, by June 1, 2009, outlining your intentions to correct the noted deficiencies. Please retain a copy of this report for a period of not less than ten years; it should be available to the Department and/or the public upon request. If you have any questions, please contact me at the Region 1-Anderson EQC Office, (864) 260-5569.

Sincerely,

Ina Richards

tra Licharde

cc: Bureau of Water, Compliance Section enclosure-valve worksheet



#### C. Earl Hunter, Commissioner

Promoting and protecting the health of the public and the environment.

David Shoemaker Georgia Water and Wells 259 Wynburn Avenue Athens, Georgia 30601

April 10, 2009

BECEIAED

JUL 20 2010

PSC SC CLERK'S OFFICE

RE:

Port Bass II

System # 3750012

Dear Mr. Shoemaker:

On March 31, 2009, a sanitary survey of the above referenced system was conducted by the South Carolina Department of Health and Environmental Control (Department) personnel to determine compliance with the State Primary Drinking Water Regulations. An overall rating of **NEEDS IMPROVEMENT** has been given for this survey. Following are comments and/or recommendations on items noted during the inspection. These items should be addressed immediately to help ensure that the water system is able to provide a continuous supply of safe drinking water to the customers/consumer. The headings and item numbers listed on the following page(s) correspond with the headings and item numbers listed on the enclosed Public Water System Sanitary Survey Report.

## [REMEMBER TO DISINFECT THE WELL AND SYSTEM AFTER ANY REPAIRS/UPGRADES ARE MADE TO THE WELL, STORAGE TANK, OR PIPING].

Please respond to this office, in writing, by June 1, 2009, outlining your intentions to correct the noted deficiencies. Please retain a copy of this report for a period of not less than ten years; it should be available to the Department and/or the public upon request. If you have any questions, please contact me at the Region 1-Anderson EQC Office, (864) 260-5569.

Sincerely.

Ina Richards

cc: Bureau of Water, Compliance Section enclosure-valve worksheet



#### C. Earl Hunter, Commissioner

Promoting and protecting the health of the public and the environment.

RECETIO

Georgia Water and Well David Shoemaker 259 Wynburn Avenue Athens, Georgia 30601

April 6, 2009

JUL 20 2010

PSC SC CLERK'S OFFICE

RE:

Timberlake I System # 3750006

Dear Mr. Shoemaker:

On March 31, 2009, a sanitary survey of the above referenced system was conducted by the South Carolina Department of Health and Environmental Control (Department) personnel to determine compliance with the State Primary Drinking Water Regulations. An overall rating of SATISFACTORY has been given for this survey. Following are comments and/or recommendations on items noted during the inspection. These items should be addressed immediately to help ensure that the water system is able to provide a continuous supply of safe drinking water to the customers/consumer. The headings and item numbers listed on the following page(s) correspond with the headings and item numbers listed on the enclosed Public Water System Sanitary Survey Report.

### [REMEMBER TO DISINFECT THE WELL AND SYSTEM AFTER ANY REPAIRS/UPGRADES ARE MADE TO THE WELL, STORAGE TANK, OR PIPING].

Please retain a copy of this report for a period of not less than ten years; it should be available to the Department and/or the public upon request. If you have any questions, please contact me at the Region 1-Anderson EQC Office, (864) 260-5569.

Sincerely,

Sua Richards

Bureau of Water, Compliance Section

CC:



### C. Earl Hunter, Commissioner

Promoting and protecting the health of the public and the environment.

BECEINEL

Georgia Water and Well David Shoemaker 259 Wynburn Avenue Athens, Georgia 30601

April 10, 2009

JUL 2 0 2010

PSC SC CLERK'S OFFICE

RE:

Timberlake II System # 3750007

Dear Mr. Shoemaker:

On March 31, 2009, a sanitary survey of the above referenced system was conducted by the South Carolina Department of Health and Environmental Control (Department) personnel to determine compliance with the State Primary Drinking Water Regulations. An overall rating of NEEDS IMPROVEMENT has been given for this survey. Following are comments and/or recommendations on items noted during the inspection. These items should be addressed immediately to help ensure that the water system is able to provide a continuous supply of safe drinking water to the customers/consumer. The headings and item numbers listed on the following page(s) correspond with the headings and item numbers listed on the enclosed Public Water System Sanitary Survey Report.

# [REMEMBER TO DISINFECT THE WELL AND SYSTEM AFTER ANY REPAIRS/UPGRADES ARE MADE TO THE WELL, STORAGE TANK, OR PIPING].

Please retain a copy of this report for a period of not less than ten years; it should be available to the Department and/or the public upon request. If you have any questions, please contact me at the Region 1-Anderson EQC Office, (864) 260-5569.

Sincerely,

Ma Lihards
Ina Richards

cc: Bureau of Water, Compliance Section enclosure-valve worksheet